

25X1

R 0723Z APR 70
 FM NPIC WASHDC
 TO AIG 7840

1970 APR 7 23 37Z

OUT 69651

25X1

RUHJPSA/COMSEVENTHFLT
 RUHJRLA/CTF76
 RUHJPHA/CTF77
 RUMUGKD/COMNAVFORV
 RUADJKA/5AF FUCHU AS
 RUECSDO/NFOIO
 BT
 C O N F I D E N T I A L
 CITE NPIC 8289.

SUPIR:CA SER:000394 PRJ:GA MSN:T00166 DTZ:700227H
 DAY PHOTO. CAMERA ON 0136Z, OFF 0520Z. CAMERA IS IRIS
 REF (A) 548 RTG IPIR SER. KH0024 FEB 70. REF (B) PADAF SUPIR
 SER. PG0010 FEB 70. REF (C) LA/VN SADL 3-70, ICOD 23 FEB 70
 THIS MESSAGE SUPPLEMENTS INFORMATION CONTAINED IN REFS.

PART I. NONE

PART II. SIGNIFICANT RESULTS

C. CHANGE AND OB ITEMS

I [REDACTED] SERVICEABILITY ROUTE 321
 CTY:LA 211011N1011306E INT:GCC GCO CL WHD
 URG: SLR: IFR: UTM:47QQD303442
 STA:OPR
 RMK:ROUTE 321 APPEARS SERVICEABLE AND SUSTAINS LIGHT TRAFFIC FOR 8.5 NM FROM MUONG SING AT 21-11-19N 101-09-19E (UTM QD237712) THE CHINA/LAOS BORDER WHERE IT CONNECTS WITH ROUTE 411. 01-12-17N 101-15-10E (QD338463).
 [REDACTED]
 MPR:AMS SERIES L7015, SHEETS 5251-II & III

DISTRIBUTION		
CY	OFFICE	PI
	FILE	
	PP&B/RD	
	SICUR.	
LL.	TSSG	
SUPIR	FSG/OC	
	RED	
	REPRO	
	AID	
	IEG	
	IEG/OD	
	SCEN	
	WEST	
	EAST	
	M&S	
	IEG/WHD	
	IAS	
	DIA-XX4	
	SPADOR	
	DIA-AP	
	CMX	

ITEM [REDACTED] SERVICEABILITY ROUTE 49
 CTY:LA 213430N1015311E INT:GCC GCO CL W
 URG: SLR: IFR: UTM:47QQD989882
 STA:OPR
 RMK:ROUTE 49 IS SERVICEABLE AND SUSTAINS MODERATE TRAFFIC FOR 22.5 NM FROM THE CHINA/LAOS BORDER AT 21-28-00N 101-50-06E (UTM QD937763) TO ITS JUNCTION WITH ROUTE 4 AT 21-35-47N 101-59-16E (RD093909).
 [REDACTED]
 MPR:AMS SERIES L7015, SHEETS 5351-I AND 5352-II.

ITEM [REDACTED] NEWLY CONSTRUCTED ROAD
 CTY:LA 213720N1020530E INT:GCO CL W
 URG: SLR: IFR: UTM:48QSJ989937
 STA:OPR
 RMK:A NEW ROAD EXTENDS SOUTH FOR 3 NM FROM A JUNCTION WITH ROUTE 493 AT 21-38-40N 102-05-52E (UTM SJ996961) TO ITS SOUTHERN TERMINUS AT THE VILLAGE OF BO KONG AT 21-36-12N 102-05-31E (SJ989922). BOTH ROUTE 493 AND THIS ROAD APPEAR SERVICEABLE AND SUSTAIN MODERATE TRAFFIC.
 [REDACTED]

25X1

25X1

— 2 —

MPR:AMS SERIES L7015, SHEETS 5452-III

ITN [REDACTED] SERVICEABILITY ROUTE 4P
 CTY:LA 214158N1020755E INT:GCO CL W 25X1
 URG: SLR: IFR: UTM:48QTK033021

URG: SLR: IFR:
 STA:OPR
 RMK:ROUTE SEGMENT 4P IS SERVICEABLE AND SUSTAINS MODERATE
 TRAFFIC FOR 16.5 NM FROM ITS WESTERN JUNCTION WITH ROUTE 49 AT
 21-35-47N 101-59-16E (UTM RD093909) TO ITS EASTERNMOST TERMINUS
 AT THE VILLAGE OF HAT SA ON THE WESTERN BANK OF THE NAM OU RIVER
 AT 21-44-26N 101-12-00E (TK103065).

[REDACTED] MPR:AMS SERIES L7015, SHEETS 5352-II AND 5452-III 25X1

ITN [REDACTED] PROBABLE BRIDGE CONSTRUCTION ROUTE 46A
 CTY:LA 203826N1015839E INT:GCO CL W 25X1
 URG: SLR: IFR: UTM:47QRC103849

STA:UCO
 RMK:PROBABLE CONSTRUCTION OF A BRIDGE OVER THE NAM NGAO (STREAM)
 IS OBSERVED 3 NM SOUTH OF MUONG SAI ON ROUTE 46A AT 20-38-26N
 101-58-39E (UTM RC103849).

[REDACTED] MPR:AMS SERIES L7015, SHEET 5350-II 25X1

EOM
 GP-1

C O N F I D E N T I A L [REDACTED]

25X1

END OF MESSAGE